

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: January 14, 2022
TO: Mitsubishi Motors US & Puerto Rico Dealer Principals, General Managers,
Service Managers, and Parts Managers
RE: TSB-21-42A-011 Modified Hood for Hood Flutter - 2022 Outlander
TIN NO. TIN-22-42A-001

.....

AFFECTED VEHICLES: 2022 Outlander

PURPOSE

MMNA recently released TSB-21-42A-011 (Modified Hood for Hood Flutter – 2022 Outlander), which describes different countermeasures based on the vehicle production date.

As a reminder, vehicles produced **after 11/11/2021** have the reinforced hood installed on the production line and do not require hood replacement or the other previously released TSB's. This new hood with the added reinforcement has essentially eliminated the flutter condition. These vehicles are **now arriving** at your dealerships so please be aware of this clean point.

In the extremely rare case that a customer expresses a hood flutter concern on a 2022 Outlander built after 11/11/2021 – please do not replace the hood – just follow the procedure outlined in TSB-21-42A-011 for this scenario.