

**** TECHNICAL INFORMATION NOTICE ****

DATE: January 21, 2022
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Odometer Calibration after Instrument Cluster/Meter Replacement
TIN NO. TIN-22-54-002

.....

AFFECTED VEHICLES: 2022 Outlander

PURPOSE:

When replacing an Instrument Cluster/Meter assembly in a 2022 Outlander for any reason, the meter does not need to be sent to the Instrument Cluster Store for odometer calibration. In order to calibrate the instrument cluster there is a procedure in the service manual to write the original mileage back to the Instrument Cluster/Meter assembly. Please follow the steps below:

Service Manual - Vol 5 - "Meter, Warning Lamp & Indicator"

After replacement of the Instrument Cluster/Meter assembly:

- ❖ Drive the vehicle under the following conditions.
 - Drive the vehicle over 18.6 mph/30 kmh
 - Drive over a distance of 0.6 miles/1km
- ❖ Verify original mileage is displaying on the vehicle.

Info

The mileage is stored in other control units such as the ABS C/U and is written to the Instrument Cluster/Meter assembly.



NOTE:

The odometer mileage of the combination meter is also stored and memorized in the ABS actuator and electric unit (control unit). When driving 1 km or more after replacement of the combination meter, the memorized mileage in the ABS actuator and electric unit (control unit) is written into the new combination meter.

Note: Please follow all Warranty Policy and Procedure steps when submitting claims.