

Classification:

KS19-010B

Reference:

ITB19-009B

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

January 14, 2022

INTELLIGENT KEY DOES NOT WORK AFTER BATTERY REPLACEMENT

APPLIED VEHICLES: 2019 QX50 (J55) 2019 Q50 (V37)
2019 QX60 (L50) 2019 Q60 (V37)
2019 QX60 Hybrid (L50H)

This bulletin is no longer active.

Please discard previous versions of ITB19-009.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 4, 2019	ITB19-009	Original bulletin published
February 1, 2021	ITB19-009a	Classification number updated
January 14, 2022	ITB19-009B	Bulletin no longer active