

Classification:

Reference:

 COPYRIGHT© NISSAN NORTH AMERICA, INC.
 Date:

KS21-005

ITB22-001

January 14, 2022

INTELLIGENT KEY SERVICE INFORMATION

APPLIED VEHICLES: 2022 QX60 (L51)

SERVICE INFORMATION

- When replacing the Intelligent Key unit (hands free module), **ALWAYS** replace it with a new one.
- Module configuration **MUST BE** performed before NATS initialization (key registration). Once NATS initialization has been performed, portions of the configuration are locked and can no longer be changed.
- When replacing the Intelligent Key unit, it is critical to follow the work procedure in the ESM.
 - Refer to the ESM: **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT**

NOTICE

To prevent damage to the Intelligent Key unit, perform module configuration **BEFORE** NATS initialization.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 14, 2022	ITB22-001	Original bulletin published

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.