



SERVICE BULLETIN

Classification: KS20-037B	Reference: NTB20-073B	Date: January 26, 2022
------------------------------	--------------------------	---------------------------

INTELLIGENT KEY UNIT SERVICE INFORMATION

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2022 Pathfinder (R53)
2021-2022 Rogue (T33)
2020-2022 Sentra (B18)

SERVICE INFORMATION

- When replacing the Intelligent Key unit (hands free module), **ALWAYS** replace it with a new one.
- Module configuration **MUST BE** performed before NATS initialization (key registration). Once NATS initialization has been performed, portions of the configuration are locked and can no longer be changed.
- When replacing the Intelligent Key unit, it is critical to follow the work procedure as detailed in the ESM.
 - For Pathfinder and Rogue, navigate to **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT**
 - For Sentra, navigate to **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > INTELLIGENT KEY UNIT > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT**

NOTICE

To prevent damage to the Intelligent Key unit, perform module configuration **BEFORE** NATS initialization.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 14, 2020	NTB20-073	Original bulletin published
January 28, 2021	NTB20-073a	Classification number updated
January 26, 2022	NTB20-073B	APPLIED VEHICLES revised

