



SERVICE BULLETIN

Classification: EL20-038A	Reference: NTB20-074A	Date: January 26, 2022
------------------------------	--------------------------	---------------------------

BCM SERVICE INFORMATION

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2022 Pathfinder (R53)
2021-2022 Rogue (T33)
2020-2022 Sentra (B18)

SERVICE INFORMATION

- When replacing the BCM, **ALWAYS** replace it with a new one.
- Module configuration **MUST BE** performed before pairing the BCM and Intelligent Key unit. Once the BCM and Intelligent Key unit have been paired, portions of the configuration are locked and can no longer be changed.
- When replacing the BCM, it is critical to follow the work procedure as detailed in the ESM.
 - For Pathfinder and Rogue, navigate to **ELECTRICAL & POWER CONTROL > BODY CONTROL SYSTEM > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING BCM**
 - For Sentra, navigate to **ELECTRICAL & POWER CONTROL > BODY CONTROL SYSTEM > BASIC INSPECTION > INSPECTION & ADJUSTMENT > ADDITIONAL SERVICE WHEN REPLACING CONTROL UNIT (BCM)**

NOTICE

To prevent damage to the BCM, perform module configuration **BEFORE** pairing the BCM and Intelligent Key unit.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 14, 2020	NTB20-074	Original bulletin published
January 26, 2022	NTB20-074A	APPLIED VEHICLES revised

