

2022 Ascent

2. Concern: Roof A/C not working

Cause: Trouble shot with Ryan at Pleasureway. No data from G12

Correction: R & R A/C temp sensor

Time: 1.5 hours 1.0 approved maximum.