

2021 Ontour

1.Concern: Electrical not working properly in coach

Cause: Inverter bad

Correction: Found battery voltage at 12.7 plugged into shore power. Checked DCM3 page at 0% charge on battery. Started generator 12.7 volts, 0 amperage charging. Charged batteries for (2) hours and still 0%. Need to R & R inverter

Time: 2 hrs **2.0 approved. Spyder is sending part as warranty as you specified.**