



Preliminary Information

PIP4723F Website for AFIT, TPM, GR8, MIT, PICO Scope and VDR Updates

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|--------|--------|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| All | All | 1995 - 2022 | All | All | All | All |

Supersession Statement

This PI was superseded to include model year 2022 vehicles. Please discard PIP4723E.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

If you need to download or update the AFIT, TPM, GR8, MIT, PICO Scope or VDR tools, follow the steps below:

- 1. Log into GM global connect.**
- 2. Click on the "Departments" dropdown menu and select "Service".**
- 3. Under "Applications" on the service page, select "Special Tools and Software updates".**
- 4. You will now be re-directed to www.gmtoolsandequipment.com (do not access this site directly as it requires the use of Global connect to allow downloads)**
- 5. Click the link under "Software Downloads" for the latest AFIT, TPM, GR8, MIT, PICO Scope or VDR software version and a new page will open.**
- 6. Click the setup links and follow instructions to update the tool.**

Note: The VDR should be updated with the latest software and programmed correctly before it is installed in a customer's vehicle for a snapshot. The VDR software version number is listed at the top of the screen when the VDR program is opened.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS