Release date:



97-21-02TT - Fault code U019900, U020000, B101729, B101715, B103611, B103629 along with Various Warnings

2/18/2022

# Condition

#### **ATTENTION:**

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN. TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
Atlas, Atlas Cross Sport, Golf, Golf Wagon, Jetta, Tiguan, Taos	2019-2022	All	All	All	All	

Revision Table						
Instance Number	Published Date	Version Number	Reason For Update			
2065172/5	2/18/22	97-21-02	Update to Service instruction.			
2065172/4	1/14/22	97-21-02	Include additional DTCs.			
2065172/1	11/12/21	97-21-02	Original publication.			

Various warning lights may illuminate, the windows may operate erratically, and several communication faults are stored.

## **Technical Background**

A poor connection in/at the door wiring harness may cause fault code U019900, U020000, B101715, B101729, B103611, and B103629 to be stored along with many other faults. This may also cause unwanted activation of certain vehicle systems, such as the windows opening/closing by themselves.

### Service

Check the wiring harness at the affected A-pillar connection, both the body harness and door harness side. If there are not any connection issues found, it is recommended to replace the affected door harness and retest.

## **Additional Information**

© 2022 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.