

February 2, 2022
CAL WS 91-002

Subject: Seat Belt Bolt Inspection

Make: Western Star
Model: 4700 and 4900
Model Years Affected: 2022
Build Date: 3/8/2021

Customers	VINs
[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]

DTNA has learned that a small number of Western Star vehicles underwent a process to manually tighten seat belt bolts that was outside of our standard manufacturing process.

The vehicles are documented to have had the seat belt bolts installed properly, in compliance with relevant Federal Motor Vehicle Safety Standards and internal DTNA specifications, but one loose seat belt bolt was found on one vehicle in pre-delivery inspection prior to delivery to the ultimate purchaser.

Therefore, to confirm that no other vehicle escaped DTNA's multiple quality checks, DTNA requests that you follow the included instructions to check the seat belt bolts on the vehicles listed above.

We apologize for any inconvenience and appreciate your attention in verifying vehicle quality.

February 2, 2022
CAL WS 91-002

Subject: Seat Belt Bolt Inspection

Check that the seat belt fasteners on both the driver and passenger sides are fully seated and at the correct torque value of 41 lbf•ft (55.6 N•m).

Please contact your DSM if an issue is found.

