

Subject: UPHOLSTERY SURFACE STAINS	M-Tips No.: MT-001/22
	Last Issued : 02/04/2022

BULLETIN NOTES

This M-Tip supersedes the previously issued M-Tip(s) listed below: The changes are noted in Red.

Previous M-Tips:	Date(s) Issued:
MT-030/15	01/20/2017

APPLICABLE MODEL(S)/VINS

2013-2022 CX-5	2016-2021 CX-3	2020-2022 CX-30
2014-2022 Mazda3	2016-2022 CX-9	2022 MX-30
2014-2021 Mazda6	2016-2022 MX-5	

DESCRIPTION

Some customers may report concerns with interior upholstery surface stains particularly on high contact areas (e.g.: steering wheel, door panels, shifter...etc.). This may be caused by skin oils or chemicals such as hand lotions.


REPAIR PROCEDURE

Use a clean towel dampened in leather/vinyl cleaner or mild soap to clean the steering wheel.

NOTE: Upholstery maintenance and care information can also be found in the Owner's Manual.

Example:

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication.
To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com . All contributions become property of MNAO, which assumes permission to publish them without further consideration.



Steering wheel stained

Steering wheel after cleaning

Warranty Compliance Note:

Parts replacement for this concern is not covered under Mazda's warranty policy.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com. All contributions become property of MNAO, which assumes permission to publish them without further consideration.