# News Channel Update |

## Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services
RE: Service Campaign Launch Notification	
Update MBUX Control Unit - Navigation	
MY21-22 A-Class (177 platform), CLA-Class (118	
platform), CLS-Class (257 platform), E-Class (213 and	DATE: February 4, 2022
238 platform), GLA-Class, GLB-Class (247 platform),	
GLC-Class (253 platform), GLE-Class, GLS-Class (167	
platform), and GT-Class (290 platform)	

### IMPORTANT NEW SERVICE CAMPAIGN LAUNCH INFORMATION

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

**Gregory Gunther** 

Department Manager, Vehicle Compliance & Analysis



# News Channel Update | Vehicle Compliance & Analysis

Service Campaign Launch Notification		February 4, 2022				
Campaign No. :	Campaign Desc. :	Update MBUX Control Unit -				
2022010008	21P5497301	Navigation				
2021-2022 A-Class (177 platformass, GLB-Class (247 platform	orm), CLA-Class (118 platform), CLS- n), GLC-Class (253 platform), GLE-Cl	ne MBUX control unit software in 38,293 Model Year ("MY") -Class (257 platform), E-Class (213 and 238 platform), GLA- ass, GLS-Class (167 platform), and GT-Class (290 platform) d in VMI as "OPEN" on February 4, 2022.				
	Backgrou	nd				
Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2021-22 A-Class (177 platform), CLA-Class (118 platform), CLS-Class (257 platform), E-Class (213 and 238 platform), GLA-Class, GLB-Class (247 platform), GLC-Class (253 platform), GLE-Class, GLS-Class (167 platform), and GT-Class (290 platform) vehicles, the software for the MBUX control unit does not correspond with the latest series production configuration, and subsequently, navigation may not be available.						
What We're Doing		MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will update the MBUX control unit software.				
Parts The Remedy is available and can be performed as necessary.						
	Vehicles Aff	ected				
Vehicle Model Year(s)	2021-2022					
Vehicle Models	A-Class, CLA-Class, CLS-C GLS-Class, and GT-Class	A-Class, CLA-Class, CLS-Class, E-Class, GLA-Class, GLB-Class, GLC-Class, GLS-Class, and GT-Class				
	Vehicle Popul	ations				
Total Campaign Population	38,293					
Next Steps/Notes						
AOMS/SOMS	AOMs – This campaign ma	ay generate questions from your dealers.				
While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.						



Service Campaign Bulletin

### **Service Campaign Bulletin**



Campaign No. 2022010008, February 2022

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Various Models

Service Campaign Bulletin

Service Campaign Bulletin

Model Year 2021-2022

**Update MBUX Control Unit Navigation Software** 

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz, has determined that on certain Model Year ("MY") 2021-2022 A-Class (177 platform), CLA-Class (118 platform), CLS-Class (257 platform), E-Class (213 and 238 platform), GLA-Class, GLB-Class (247 platform), GLC-Class (253 platform), GLE-Class, GLS-Class (167 platform), and GT-Class (290 platform) vehicles, the software for the MBUX control unit does not correspond with the latest series production configuration. The possibility exists that the navigation may not be available.

#### Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 38,293 vehicles are affected.

Order No. P-SC-2022010008

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Record

Up	da	ate	mι	ultime	edia	syste	em (N	IBUX	ioo (2	ntrol	unit	soft	ware
				40-	4	~ 4 ~	~~~	~ 4 =	~=~	~	~~~		

2. Update *multimedia system (MBUX)* control unit software.

Model 118; 167; 177; 213; 238; 247; 253; 257; 290

i	•	Ensure	use of 2	XENTRY	Diagnosis	version	BD/DVD	(12/2021)	or highe

- Before starting the work procedure, install the current version of all add-ons in XENTRY Diagnosis.
- Make sure to follow the operation steps exactly as described in XENTRY Diagnosis.
- Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (greater than 12.5 V).
- If XENTRY Diagnosis is already connected to the vehicle, start with **operation step 2**.

If two or more software updates or SCN codings are performed during one workshop visit, the operation items 02-4762 and 02-5058 may only be invoiced once for each workshop order.

### **Work Procedure**

1. (	Connect	XENTRY	Diagnosis.
------	---------	--------	------------

	To do this, select menu item "Quick test view – A26/17 MBUX multimedia system (Head unit) – Adaptations – Control unit update – Updating of control unit software".  Then follow the user guidance in XENTRY Diagnosis.
3.	Disconnect XENTRY Diagnosis.

Note: The following allowable labor operation should be used when submitting a warranty claim for this repair.

### **Warranty Information**

Damage	Operation	Description	
Code	Number		
	02-9334*	Update <i>multimedia system (MBUX)</i> control unit software (with XENTRY Diagnosis connected)	0.1 h
54 973 01	02-4762**	Connect/disconnect diagnostic system (XENTRY Diagnosis)	0.1 h
	02-5058**	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h

<sup>\*</sup> The operation item is to be repeated as often as necessary.

<sup>\*\*</sup> Operation item may only be invoiced once for each workshop order!

Note: Always check ASRA for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.