



## Preliminary Information

### PIT5884A Service Park Assist Message On Trucks Not Equipped With Front / Rear Park Assist RPO 00Y or 00Z

Product Investigation Review Required

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 LTD	2022	12/15/21	1/3/2022	All	All
GMC	Sierra 1500 Limited	2022	12/15/21	1/3/2022	All	All

Involved Region or Country	North America
Additional Options (RPO)	00Z or 00Y - Not Equipped With Front / Rear Park Assist
Condition	<p>Some customers may comment of a Service Park Assist message displayed on the DIC when the vehicle is started. These vehicles will have RPO 00Z or 00Y, meaning that the vehicle's front and/or rear park assist was disabled and there will be no Park Assist Module installed on the vehicle. When checking for DTC's there will be none found that are related to this concern.</p> <p>For more information regarding RPO's 00Z and 00Y please see Global Connect Message GCUS-17-429.</p>
Cause	These vehicles should not be displaying a Service Park Assist message and the cause of this concern could be the wrong IPC XML file.

#### Correction:

To correct this issue, see Service Update N222357620: Inadvertent Service Park Assist System Error Message.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Please use the warranty information found in Service Update [N222357620](#) - Inadvertent Service Park Assist System Error Message

#### Version History

Version	2
Modified	01/13/2021 - Created on. 02/01/2022 - Update to correction and warranty sections.



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.