



Preliminary Information

PIT5733B Installation of Roof Beacon Light

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
Chevrolet	Silverado	2020 - 2022	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All
GMC	Sierra	2020 - 2022	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	VYU Snow Plow Prep
Condition	A Dealer or Upfitter may be looking for information on installing a roof beacon light.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 157. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

Version	3
Modified	02/13/2020 - Created on 02/12/2021 - Added 2021 Model Year 02/07/2022 - Added 2022 Model Year

