



Preliminary Information

PIP5789A Chevrolet Spark TCM Replacement Requested During The Replacement Of A CVT7 Transmission

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Spark	2020 - 2022	All	All	All	MR8

Involved Region or Country	North America
Condition	TCM replacement requested when replacing a CVT7 transmission.
Cause	After following SI diagnostics, technicians may determine that the transmission needs to be replaced.

Correction:

Please follow service information to aid in diagnosing CVT7 transmission concerns.

If diagnostics leads to replacement of the transmission engineering is temporarily asking to please replace the TCM.

Note: Please do not perform a service fast learn procedure with the old TCM in place. The fast learn procedure will erase the data that engineering is looking for.

Note: Engineering will be requesting that both the transmission and the TCM be returned to the WPC.

Version History

Version	
Modified	03/16/2021 - Created on. 02/09/2022 - Updated Model Years.

