

Subject		Market
<b>MIL ON w/DTC P013A</b>		<b>USA</b>
Service Category	Section	
Vehicle Interior	Meter/Gauge/Display	
Applicability		
2022 IS500		

**APPLICABLE VEHICLES**

2022	IS500
------	-------

**CONDITION**

Customers may complain of a MIL ON condition. DTC P013A may be retrieved from the engine ECM:

- P013A – *Oxygen Sensor Slow Response – Rich to Lean Bank 1 Sensor 2*

**RECOMMENDATIONS**

- Block the exhaust outlets and check for exhaust leaks between the LH exhaust manifold and front exhaust pipe.
- Create a TAS case.
- Perform an All-Data Health Check and attach the Techstream file to the TAS case.

If diagnosis occurs on a holiday or weekend, continue with diagnosis and repair. Save all parts and Techstream file. Contact TAS at the next opportunity.

*Note:* Exhaust gaskets are non-reusable parts and should be replaced if the exhaust system is disassembled.

**LINK REFERENCES**

This Tech Tip does not contain any link references