

Subject		Market	
4WD Inoperative, Lights Flashing on Dash		USA	
Service Category	Section		
Drivetrain	Transfer/4wd/Awd		
Applicability			
MY18-22 Tacoma			

APPLICABLE VEHICLES

2018-2022

Tacoma

CONDITION

Water intrusion to the ADD actuator is currently being investigated as a cause of 4WD inoperative complaints. P17A0 and P17A4 DTCs may set for this condition but not always.

RECOMMENDATIONS

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references