

N222363820 – Driver’s Side Rear Wheel Liner Instructions

Vehicles Involved: 2022 Chevrolet Blazer

IMPORTANT Information

The referenced vehicles were placed on Stop Delivery on March 17, 2022, or March 21, 2022. The following steps will be required to release these vehicles for sale.

1. The Driver’s Side Rear Wheel Liner will be sent to your Dealership Parts Department (ATTN: Parts Manager) for installation on these vehicles (over the next few days). Note: The Wheel Liner part and Attachments will be sent at no charge. The involved VIN(s) and a copy of this Instruction Form for N222363820 will also be included for informational purposes with the part shipment.
2. Once the parts have arrived, follow the Service Procedure Instructions below to complete the wheel liner installation.
3. **IMPORTANT:** Once the wheel liner installation is complete, submit a transaction into GWM using the labor operation 9106206 and note these special instructions (**a. and b.**).
 - a. **Do Not Submit for Part Cost - Submit for the dealer parts handling allowance ONLY in Misc. Net Items. (\$177.75 multiplied by your approved parts handling allowance. Example - Part Handling Allowance: \$177.75 x 40% = \$71.10).**
 - b. **Note: Submitting a part number on the transaction will result in claim rejection.**

Part Information

Quantity	Part Name	Part Cost
1 pkg	Rear Wheelhouse Liner Installation Kit	\$0.00


Warranty Information

Submit a transaction in GWM using the table below. All transactions must be submitted as a ZFAT transaction type.


Labor Operation	Description	Labor Time	Trans. Type	Net Item/Misc.
9106206	Left Rear Wheelhouse Liner Installation/Area Inspection	0.3	ZFAT	N/A
9105902	Build Sheet Inspection Email	0.1	ZFAT	N/A

Service Procedure

1. Lift the vehicle. Refer to *Lifting and Jacking the Vehicle* in SI.
2. Remove the left rear wheel. Refer to *Tire and Wheel Removal and Installation* in SI.



3. Inspect the fuel filler neck and wire harness circled above for any damage.
 - a. If damage is found, open a new warranty line and repair the components as necessary before proceeding to step 4.
 - b. If no damage is found, proceed directly to step 4.
4. Install the Left Rear Wheelhouse Liner. Refer to *Rear Wheelhouse Liner Replacement* in SI.
5. Reinstall the left rear wheel. Refer to *Tire and Wheel Removal and Installation* in SI.
6. Lower the vehicle.



TARJETA DE INSPECCION ENSEMBLE GENERAL L-2

PVE: 222363820
 Mod: 1NK25

CAN

CAN: 222363820
 VIN: 30MBR52N31R1471

REF: 1000

CARROCERIAS

ENRACE PTA A CTO L/I

AB COTR A SALPICADERA

ABERTURA EN V SALPA PTA R/L

ABERTURA LAMPARA DERECHA A PORTON

ALINEACION SALPICADERA A PUERTA

PUERTA salpicadera AB ENR

PINTURA

1. 22 Pintura

VESTIDURAS

AB ENR APPLIQUES

AB ENR CANTILLAS

AB ENR DLO

LAMPARAS TRAS

CHASIS

CABLE BATERIA POSITIVO

PORTON FASCIA AB ENR

FARO FASCIA AB ENR

Fe tar de delovate

MANUAL DE REPARACIONES | PARTES DESELLADAS | UER TOR | CLERS | CAN E REP | ETC

1000 electrica 100x

- Remove the build inspection sheet shown above from the glove box. Scan or photograph the sheet(s) and send via email to:

josemiguel.fernandezalvarez@gm.com

- After the document has been successfully emailed to the address above, please discard. (Note: If there is no build inspection sheet in the glove box, note on the repair order comment section that it is missing, and disregard Step 7).

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6100
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 28, 2022

Subject: Update to Stop Delivery Order for N222363820 – Driver's Side Rear Wheel Liner – **Updated Instruction Sheet Attached**

Models: 2022 Chevrolet Blazer

To: Select General Motors Dealers in Michigan and Ohio Only

Attn: Dealer Principal, Sales/Service/Parts Managers

On March 17, 2022, or March 21, 2022, we advised of the stop delivery of certain VINs for 2022 model year Chevrolet Blazer vehicles.

The attached **updated** Instructions document details important information regarding the required steps to complete the release of these vehicles from Stop Delivery. It also provides part information, transaction information (including labor code), and the service procedure.

It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification until the defect is remedied.

Important: Parts will be shipped and are expected to arrive to your dealership in the next few days. Included in the box are the attached set of instructions and a note stating to which VIN the driver's side rear wheel liner needs to be installed.

Until all steps in the instruction document have been completed, these involved vehicles that are in your possession must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration purposes or any other dealer use.

Attached is a list of the involved BACs and the associated VINs.

The Investigate Vehicle History (IVH) screen in the Global Warranty Management (GWM) system was updated with the new labor code on March 24, 2022. The following statement will be in IVH in the Description field: For Dealers that require a copy of the remedy instruction sheet please contact TAC and Reference AIT3464.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS