

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6104
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 28, 2022

Subject: N222360030 - Customer Satisfaction Program
Incorrect Roof Paint Color – US Only

Models: 2022 Chevrolet Blazer
Equipped with Top Color-Black (96) (RPO 41T)

To: All General Motors Dealers

General Motors is releasing Customer Satisfaction Program N222360800 today. The total number of U.S. vehicles involved is approximately 2. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin the week of April 11, 2022.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated March 29, 2022, or sooner. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS

Customer Satisfaction Program

N222360030 Incorrect Roof Paint Color – US Only



Release Date: March 2022

Revision: 00

Attention: This program is in effect until April 30, 2024.
 This Customer Satisfaction involves only 2 VINs listed below.
 3GNKBERS8NS136145
 3GNKBERS5NS136331

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Blazer	2022	2022	41T	Top Color-Black (96)

Involved vehicles are marked “open” on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2022 model year Chevrolet Blazer vehicles may have been built with the body-colored roof instead of the black two-tone roof color.
Correction	Dealers will inspect for the correct roof paint color (black) and if necessary, provide the customer with a reimbursement check in the amount of \$550.00 if the roof is the body paint color.

Parts

No parts are required.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9106220	Inspect Roof Color	0.2	ZFAT	N/A
9106212	Customer Reimbursement Check Issued	N/A	ZFAT	*

* Submit the dollar amount reimbursed to the Customer in Net/Reimbursement. The amount identified in Net Item is the \$550.00 dealer check issued to a customer. Record the check number in the Invoice Number field. Record the VIN on the check. Submit \$20.00 administrative allowance in Net/Admin Allowance.

Service Procedure

Important: Dealers are to verify these three pieces of information prior to issuing a reimbursement check:

1. Original Owner Letter provided by General Motors.
2. Vehicle registration.
3. Driver's license or state ID - verify that it matches the registration and owner letter.



6020219

1. Inspect the roof for the correct paint color:
 - 1.1. If the roof color is NOT correct (1), proceed to step 2.
 - 1.2. If the roof color is correct (2), no further action is required.
2. Issue the customer a reimbursement check in the amount of \$550.00. Record the check number in the Invoice Number field and record the VIN on the check.

Customer Satisfaction Program

N222360030 Incorrect Roof Paint Color – US Only



Dealer Responsibility

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this program must be held and inspected/repaired per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, through April 30, 2024. Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this program enters your vehicle inventory or is in your facility for service through April 30, 2024, you must take the steps necessary to be sure the program correction has been made before selling or releasing the vehicle.

Dealer Reports

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

Customer Notification

USA - General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**

Customer Satisfaction Program

N222360030 Incorrect Roof Paint Color – US Only



April 2022

This notice applies to your vehicle, **VIN:** _____

Dear General Motors Customer:

We have learned that your 2022 model year Chevrolet Blazer vehicle may have been built with the body-colored roof instead of the black two-tone roof color.

Your satisfaction with your Chevrolet Blazer is very important to us, so we are announcing a program to correct this issue.

What We Will Do: Your GM dealer will provide you with a reimbursement check in the amount of \$550.00. This reimbursement is available to you until **April 30, 2024**.

What You Should Do: To limit any possible inconvenience, we recommend that you contact your GM dealer as soon as possible to begin the reimbursement process. Please provide this customer letter, your driver's license or state ID and vehicle registration to the dealer to receive your reimbursement check.

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

For the hearing or speech impaired, please contact our Customer Assistance Center using the Telecommunication Relay Service by dialing 711 then providing the appropriate Customer Assistance Center number for your vehicle.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	711 / 1-800-833-2438
Puerto Rico – English	1-866-467-9700	
Puerto Rico – Español	1-866-467-9700	

We want you to know that we will do our best, throughout your ownership experience, to ensure that your Chevrolet Blazer vehicle provides you many miles of enjoyable driving.

Neelie O'Connor
Global Executive Director
Customer Experience Operations

N222360030