



# Technical Service Bulletin

---

## 01 PSS MIL on DTC P240700 Evap leak detection pump circuit

01 22 19 2066675/1 March 29, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2022	All	Gasoline Engine

## Condition

### Customer states:

- MIL Light On.

### Workshop findings:

- The following DTC may be stored Passive/Static in the Engine control module, J623 (address word 001):  
**P240700**

The event memory must not contain further relevant entries.

## Technical Background

Not Applicable.

## Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

## Service

1. Explain to the customer that a solution is expected to be available by the end of the 4<sup>th</sup> quarter of 2022 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since it will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Access Audi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.



# Technical Service Bulletin

---

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles</li><li>• G10 for CPO Covered Vehicles – Verify Owner</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	2048		
<b>Damage Code:</b>	0040		
<b>Diagnostic Time:</b>	GFF – Checking and clearing fault codes included in existing labor operations	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2066675/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references in this TSB (**2066675**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or



# Technical Service Bulletin

---

otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.