Subject: Engineering Information - (for Pictures Only) - Front Brake Splash Shield Contacting Rotor

This PI has been revised to end the need for information from the field. Please discard PIE0674.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer	2021	2022	-	-	-	-

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released December 14, 2021 Revised March 16, 2022 – Ended the need for further information from the field.