

**WMM7 Addendum**

**Vehicles Affected**

Models	Model Year	Model Type	VIN Range
Specified in campaign literature	Specified in campaign literature	Specified in campaign literature	Specified in campaign literature

**Revision History**

Revision	Release Date	Changes
0	March 16, 2022	Original document
1	March 30, 2022	Added device replacement advice

**Technical Background**

Note the following additional information tips related to WMM7. This ATI is not a substitute or replacement for the campaign TI.

**Service Information**

Use the WMM7 campaign TI for workshop instructions, details, and references. This document contains four additional points.

1. The non-campaign part number for the 4G modules is 958 035 620 J.
2. You must perform device replacements according to the sequence given in the campaign TI. If you deviate from this sequence, the replacement will fail and VTS will not function.
3. Do not attempt to replace the device without an active contract.
4. Panamera (971) is not included in the WMM7 campaign. Do not attempt to upgrade 3G VTS modules to 4G VTS modules for vehicle programs that are not included in the campaign.

**See also:**

WM 968519, WM 968555

### Search Items

WMM7, VTS, 3G, 4G

---

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

---