

TECHNICAL TOPICS

BODY/CHASSIS



2nd Row Seat Load Through Frame Available as Lower Level Assembly

17MY-Onwards Discovery, Discovery Sport, Range Rover, RR Sport, Defender

Customer Voice:

- A customer may report that the load through center seat does not fold properly.

Technical Description:

- This may be caused by the latch or latch release cable malfunction.

Status:

- Previously the complete 60% 2nd row seat frame on 60/40 seated models had to be replaced to service the latch or latch cable. Now the load through back section is available as a lower level service part.
- Please refer to the Electronic Parts Catalog (EPC) with the VIN for the correct lower level assembly part number should a customer express a concern.
- The replacement procedure has been added to the Workshop Manual, section 501-10: Seating > Removal and Installation > Second Row Center Seat Backrest.

