TECHNICAL TOPICS BODY/CHASSIS





2nd Row Seat Pivot Mechanism Available as Lower Level Assembly

Customer Voice:

A customer may report that the 2nd row seat makes a ratcheting noise or is difficult to manually folding/unfolding the seat.

Technical Description:

This may be caused by a seat pivot 'Clockwork' mechanism assembly.

Status:

- The 2nd row seat 'Clockwork' assemblies have now been released as a lower. level service part.
- Please refer to the Electronic Parts Catalog (EPC) with the VIN for the correct lower level assembly part number should diagnosis of a customer concern identify a seat pivot 'Clockwork' mechanism failure.
- The replacement procedure has been added to the Workshop Manual, section 501-10: Seating > General Procedures > Second Row Seat Recline Mechanism.

17MY-Onwards Discovery, Discovery Sport, Defender











