

# TECHNICAL TOPICS

## BODY/CHASSIS



3 <sup>rd</sup> Row Seat Folding Actuator Lower Level Assembly	17MY-Onwards Discovery
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>A customer may report that the 3<sup>rd</sup> row seat backrest is stuck in the upright position.</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>This may be caused by a 3<sup>rd</sup> row seat fold motor malfunction.</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>The 3<sup>rd</sup> row seat backrest and base motors have now been released as a lower level service part, preventing the need to replace the seat frame assemblies to service the motors.</li> <li>Please refer to the lower level assembly service parts to conduct repairs wherever possible upon diagnosis of a seat fold motor failure.</li> <li>The service procedure has been added to the Workshop Manual, section 501-10: Seating &gt; Removal and Installation &gt; Third Row Seat Recline Motor or Third Row Seat Folding Actuator Motor.</li> </ul>	

