

Technical Service Bulletin

90 Horn beeps unintentionally when steering wheel is turned

90 22 56 2066712/1 April 1, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3 and S3	2022	All	Not Applicable
Q3	2019 – 2022		

Condition

Customer states:

• The horn beeps unintentionally when the steering wheel is turned.

Workshop findings:

• When turning the steering wheel, the horn beeps unintentionally.

Technical Background

Various steering column switch modules have been replaced under warranty for the condition noted above but no issues were identified with these parts. Replacing the steering column switch module in these cases did not resolve the concern.

Production Solution

Not applicable.

Service

© 2022 Audi of America, Inc.

If the customer's complaint can be reproduced, perform the following:

- 1. Remove the airbag from the steering wheel.
- 2. Turn the steering wheel to check if the horn still activates unintentionally.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

3. If the issue is resolved with the airbag removed from the steering wheel, continue by inspecting the airbag assembly for the cause of the issue.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2066712) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.