



Preliminary Information

PIT5901 Service Instrument Cluster Message at Times With DTC: U3000 SYM 09

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Suburban	2022	All	All	All	All
Chevrolet	Tahoe	2022	All	All	All	All
GMC	Yukon Models	2022	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UDD
Condition	Some customers may experience a "Service Instrument Cluster" message in the DIC (Driver Information Center) at times with DTC: U3000 SYM 09
Cause	This concern is caused by a software anomaly in the Instrument Panel Cluster (IPC)

Correction:

If you experience this concern, please do not replace IPC or any parts on the vehicle.

Updated software is being developed to address this concern and the PI will be updated at a later date with the repair.

Additional SI Keywords

inop, inoperative, module,

Version History

Version	1
Modified	03/22/2022 - Created on



GENERAL MOTORS