



Subject		Market
Engine Oil Pan Leak		USA
Service Category	Section	
Engine/Hybrid System	Lubrication	
Applicability		
2017-2022 RX350		

APPLICABLE VEHICLES

2017-2022	RX350
-----------	-------

CONDITION

Some 2017-2022 RX350 vehicles may experience an engine oil leak condition from the No.2 Oil pan. This issue is currently under investigation. Please take detailed pictures of the location of the oil pan leak condition before repair.

RECOMMENDATIONS

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. Please take a detailed picture of the location of the untouched oil pan leak condition and attach photos to the TAS case. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references