Service Alert

Mazda North American Operations Irvine, CA 92618-2922



Subject:			
AUXILIARY KEY BLANK CUTTING PROCEDURE	Service Alert No.: SA-016/22		
	Last Issued : 04/04/2022		

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

1 7		
Previous Service Alert	Date(s) Issued:	
SA-030/21	06/15/21 and 05/04/21	
SA-004/20	12/14/20, 07/06/20, 05/11/20 and 01/19/20	
SA-045/19	10/30/19	

APPLICABLE MODEL(S)/VINS

2014- <mark>2022</mark> Mazda3	2016- <mark>2022</mark> CX-3	2013- <mark>2022</mark> CX-5	2016- <mark>2022</mark> MX-5
2014-2021 Mazda6	2020- <mark>2022</mark> CX-30	2016- <mark>2022</mark> CX-9	2022 MX-30

DESCRIPTION

There are currently 2 methods for cutting a new auxiliary key blank.

- · A. Auxiliary Key Trace Cut Method
- B. Auxiliary Key Code Cut Method

Auxiliary Key Blank

REPAIR PROCEDURE

A. Auxiliary Key Trace Cut Method

If only one auxiliary key is lost/missing, some key cutting machines can trace cut a new key blank.

1. Trace cut the new auxiliary key blank(s).


B. Auxiliary Key Code Cut Method

If both auxiliary keys are lost/missing, use this method for cutting new auxiliary key blank(s).

- 1. Confirm you have access to a Mazda approved key cutting machine. See "Mazda Approved Key Cutting Machine" table.
- 2. Obtain the key code.

Page 1 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



3. Cut the new auxiliary key blank(s).

NOTE: If the drivers door key cylinder is damage due to theft/accident, the drivers door lock set is not covered by warranty policy.

- a. Replace the drivers door lock set. Go to MGSS (FRONT DOOR KEY CYLINDER REMOVAL/INSTALLATION).
- b. Update the **KEY CODE** in eMDCS by contacting Mazda Warranty via phone (800-727-6626, option #3) M-F 7am 4pm PT or by email (warrantydept@mazdausa.com) and provide the **VIN** and replacement door lock cylinder **KEY CODE** so that the new drivers door lock set key code can be updated in the eMDCS system.



Page 2 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-016/22 Last Issued : 04/04/2022

Transportation Lock-out Procedure

Auxiliary keys are locked in the vehicle upon receiving.

1. Perform B. Auxiliary Key Code Cut Method .

NOTE: Only one auxiliary key is necessary to cut in order to enter the vehicle.

- 2. After retrieving the auxiliary keys from the vehicle, dispose of the newly cut auxiliary key.
- 3. Submit transportation claim in eMDCS. Claim will be submitted for the creation of the new auxiliary key.

NOTE: Claims may be rejected if above procedure is not followed.

Mazda Approved Key Cutting Machine

	azda Approved Key Cutting Machine					
Supplier	Model	Available at	User Manual			
	PC + Flash Computerized Code Cutter & Duplicator	Mazda Tool and Equipment Website Item # CURC9100020	See attachment			
MSC	BD Laser Max Computerized Code Cutter & Duplicator	mscdirect.com MSC # 39177209	See attachment			
	Pro-Source Key Machine	mscdirect.com MSC # 90681271	See attachment			
KEYLINE	GYMKANA 994	Mazda Tool and Equipment Website Item # KYLGYMKANA	Click HERE			

Page 3 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.