

Media and/or Radio menu not available in driver display

Topic number	LI54.30-P-074584
Version	1
Function group	54.30 - Instrument cluster, display instruments, hazard warning device
Date	3/30/22
Validity	Model series 223 with code 802 Model series 206
Reason for change	

Complaint

Customer states that the Radio and/or Media menus are not available in the driver display

Note: Both menus are still present in the MBUX Display as it is not affected by the complaint

Cause

MBUX multimedia system (A26/17) software

Remedy

Perform the following steps to remedy the complaint:

1. Perform a software update of the MBUX multimedia system (A26/17)
2. Perform SCN coding of the Instrument Cluster control unit (N133/1)

Symptoms
Communication/information > Information display > Displays > Multifunction display > Multifunction display, menu > Menu items missing

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			8210NEA	