

# CAMPAIGN LAUNCH STATUS

## N654 – FRONT SEAT AIRBAGS & N623 FUEL TANK FLANGE



OWNER NOTIFIED SERVICE ACTION N654 – 20MY DEFENDER SEAT THORAX AIRBAGS	
AFFECTED MODEL	20MY DEFENDER 110
VOLUME AFFECTED	USA 63
ISSUE/REPAIR	Affected vehicles have been built with front seat thorax airbags that were manufactured with labelling depicting prototype parts. While there are no functional concerns with the airbags, a decision has been taken to replace the front driver and passenger seat airbags under this owner notified program.
REPAIR TIME	1.1 hrs + Drive In/Out
CAMPAIGN LAUNCH TARGET	April 11 <sup>th</sup> , 2022
Notes	<b>Delays in receipt of new parts has pushed the launch date into mid April.</b> All affected new units have been retailed.

SAFETY RECALL N623 - FUEL LEAKING FROM TANK OUTLET PIPE FLANGE	
AFFECTED MODELS	10-13MY Range Rover Sport and 10-16MY LR4
VOLUME AFFECTED	111,746 USA
REPAIR	Customers have reported fuel odor, occasionally liquid fuel on the ground. Retailers have diagnosed cracked fuel outlet pipe flange which will be replaced with a part of revised design. Any vehicles diagnosed with this concern today should be repaired following current processes and parts. The recall will remain open.
REPAIR TIME	1.2 hrs + Drive in/out
CAMPAIGN LAUNCH TARGET	<b>Parts availability now expected late April 2022.</b>
Notes	Retailer Notification bulletin NAS21.08.013 issued August 26 <sup>th</sup> 2021. Parts are being procured to support repair launch. Interim Owner notification October 8 <sup>th</sup> .2021. Claims must not be submitted until the recall repair is published.