

CAMPAIGN LAUNCH STATUS

H374 and N622 - EMISSION RECALLS - FUELING ADAPPTIONS



EMISSION RECALLS – N622 and H374 SECONDARY FUELING ADAPPTIONS	
AFFECTED MODELS	18MY RR Evoque, Discovery Sport, RR Velar, Jaguar F-PACE, XF, E-PACE and XE.
VOLUME AFFECTED	Jaguar 11,652 USA. 1462 CAN Land Rover 16,335 USA 1788 CAN
ISSUE/REPAIR	An Issue has been identified on certain 2018 MY vehicles with Ingenium I4 2.0L petrol engines. A Powertrain Control Module (PCM) software diagnostic monitoring routine contains a software error. Normal vehicle operation requires the Malfunction Indicator Lamp (MIL) to illuminate when the fueling adaption values are between 0.07% to 0.08% and -0.07% to -0.08% and a Diagnostic Trouble Code(s) (DTC) is set. With the software error present, the MIL will not illuminate as required. Vehicles will be corrected with a PCM software update. To be re-published adding Canadian vehicles.
REPAIR TIME	0.20 hrs + Drive In/Out
CAMPAIGN REPAIR LAUNCH	USA published February 7th, 2022., Target for Canada April 22 nd 2022
Notes	Customers will be notified by mail with request they contact Retailers to make service appointments

