## **TECHNICAL TOPICS** BODY/CHASSIS



2 <sup>nd</sup> Row Seat Pivot Mechanism Available as Lower Level Assembly	17MY-Onwards Discovery, Discovery Sport, Defender
<ul> <li><u>Customer Voice</u>: <ul> <li>A customer may report that the 2<sup>nd</sup> row seat makes a ratcheting noise or is difficult to manually folding/ unfolding the seat.</li> </ul> </li> <li><u>Technical Description</u>: <ul> <li>This may be caused by a seat pivot 'Clockwork' mechanism assembly.</li> </ul> </li> <li><u>Status</u>: <ul> <li>The 2<sup>nd</sup> row seat 'Clockwork' assemblies have now been released as a lower level service part.</li> <li>Please refer to the Electronic Parts Catalog (EPC) with the VIN for the correct lower level assembly part number should diagnosis of a customer concern identify a seat pivot 'Clockwork' mechanism failure.</li> <li>The replacement procedure has been added to the Workshop Manual, section 501-10: Seating &gt; General Procedures &gt; Second Row Seat Recline Mechanism.</li> </ul> </li> </ul>	Former Participation       Clockwork assembly 1         Plastic Part 1       1         Plastic Pa