

TECHNICAL TOPICS

BODY/CHASSIS



3rd Row Seat Folding Actuator Lower Level Assembly

17MY-Onwards Discovery

Customer Voice:


- A customer may report that the 3rd row seat backrest is stuck in the upright position.

Technical Description:

- This may be caused by a 3rd row seat fold motor malfunction.

Status:

- The 3rd row seat backrest and base motors have now been released as a lower level service part, preventing the need to replace the seat frame assemblies to service the motors.
- Please refer to the lower level assembly service parts to conduct repairs wherever possible upon diagnosis of a seat fold motor failure.
- The service procedure has been added to the Workshop Manual, section 501-10: Seating > Removal and Installation > Third Row Seat Recline Motor or Third Row Seat Folding Actuator Motor.



© Copyright, 2018 - 2021, Jaguar Land Rover Limited.

