

Technical Journal

TITLE:

Ghost DTC after software download, FLC2-C100154

REF NO: TJ 35991.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2022-03-14	STATUS DATE: 2022-03-17
FUNC GROUP: 3872	FUNC DESC: Collision avoidance	Page 1 of 2	

“Right first time in Time”

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* Add Vehicle type

Ghost DTC in FLC2 may appear after software download.

Involved DTC is FLC2-C100154 “Vision System Camera. System Programming Failures. Missing calibration” and with error message, Headlamp system malfunction service required in DIM. Please follow instructions under “Service”.

FLC2 = Forward Looking Camera 2

DIM = Driver Information Module

CSC Customer Symptom Codes

Code	Description
YI	Active High Beam (AHB)/Does not work
FL	Front fog lights/daytime running lights/Does not work
EY	Headlights/Does not work

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
FLC2	C100154	Intermittent

Technical Journal 35991.2.0

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
235							2022-2022		-	202122-202226
236							2022-2022		-	202122-202226
238							2022-2022		-	202122-202226
246							2022-2022		-	202122-202226
536	ED	E400V6					2021-2022		-	202037-202226

SERVICE:

If DTC FLC2-C100154 is set after a SW upgrade, it can be ignored.

No action needs to be taken to erase this DTC, the DTC will disappear after car go to sleep and restart of the car.

Warranty claim info:

No warranty claim accepted for a job described in this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3872.