

SSM 50743 - 2021-2022 Bronco Sport - Hiss Or Rattle Noise While Driving - Manual Park Release Cable - Built On Or Before 22-Feb-2022

Some 2021-2022 Bronco Sport vehicles built on or before 22-Feb-2022 may exhibit a hiss or rattle noise while driving. This may be due to an internal issue with the manual park release cable. If the noise is eliminated when the cable is disconnected from the transmission, install a new manual park release cable assembly. Refer to the Workshop Manual (WSM), Section 307-05 > Automatic Transmission External Controls > Removal and Installation.

APPLICABLE VEHICLES
2022 CAR: HD CX430N C-SUV
2021 CAR: HD CX430N C-SUV