



Service Bulletin

Bulletin No.: 22-NA-090

Date: May, 2022


INFORMATION

Subject: Information on Lug Nut Stainless Cap Cracking, Rusting and/or Swelling

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2019	2022				
	Silverado 2500HD/3500HD						
GMC	Sierra 1500						
	Sierra 2500HD/3500HD						

Involved Region or Country	North America, Australia, New Zealand
Condition	Some customers may comment that stainless caps on the lug nuts are cracking, rusting and/or swelling. – Refer to Examples of Damaged Lug Nut Caps section below.
Cause	This condition may be caused by the use of a worn socket/improper fitting socket when removing and installing the two piece style lug nut.
Information	Important: Use a hand torque wrench and deep well socket, alternately and evenly, to tighten the wheel nut to GM Specifications. Refer to <i>Fastener Specifications</i> in the Service Manual.

Examples of Damaged Lug Nut Caps



6052724

Version	1
Modified	Released May 04, 2022

