



SIB 46 01 22 TURN INDICATOR HOLDER LOOSE

2022-04-06


Model	Model Description
K63	S 1000 R

SITUATION

Over time, the turn indicator holders may become loose and shift away from their designated place on the fork tube.



The turn indicator holders remain loose on the fork tube even if screw is retightened.



PROCEDURE

Apply protective film to the fork tubes under the turn indicator holders.



PARTS INFORMATION

Part Number

46 51 8 560 150	VIN protective film	QTY: 4 per motorcycle
-----------------	---------------------	-----------------------

CLAIM INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Motorcycles, if applicable.

Defect code

63 13 00 37 00	Front indicator lamp loose
----------------	----------------------------

Labor Operation

63 99 000	Work Time	3 FRU
-----------	-----------	-------

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 46 01 22 Turn Indicator Signal Lamp holder loose.pdf](#)