



Thor Motor Coach Technical Service Bulletin

TSB #	TSB 22-06		
Description/Title:	Axis/Vegas Bluetooth Mic		
Affected Product Line(s):	Certain model year 2021 – 2023 Axis/Vegas		
Service Campaign # :	RC000264	Released Date:	5/23/2022
Codes:	Inspect Only: TMCTS80275Y Inspect with Repair: TMCTS80275W	Document Date:	5/19/2022
Time Allowed:	Inspect Only: 0.1 Inspect with Repair: 0.3	Document Revision:	A

Issue:

2021 – 2023 Axis/Vegas may have a Bluetooth mic that is not installed.

Tools Required:

- Zip Ties

Part(s) Required:

0494821 - MIC FOR BLUETOOTH, MULTIMEDIA RECEIVER...

Instructions:


Please see below:

1. Remove dash access cover behind radio.





2. Remove mic from its mounting “box”. Do so by pressing tabs on both sides of “box”.





3. Insert mic into the smaller plastic mic holder with tape.





4. Remove tape from mic holder and stick at desired location.



5. Run mic wires to behind the radio. Insert mic behind the radio. Secure excess wire.

