

## SERVICE ACTION

Reference number:	SA-63-1498	Issued: 11th April, 2022
Subject:	Check and Install a New Engine Start/Stop Switch	
Model(s):	DBX	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	The Americas (AMTA)	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

### Reason for this Service Action

Aston Martin has identified some DBX vehicles that must have a new level part installed for the Engine Start/Stop Switch. The new level part makes improvements to the quality of the Engine Start/Stop Switch.

Do the workshop procedure that follows to inspect, and if necessary install a new Engine Start/Stop Switch.

### Workshop Procedure

1. Remove the Engine Start/Stop Switch (refer to Workshop Manual Procedure 64.01.EE).
2. Inspect the part number label of the Engine Start/Stop Switch.
  - If part number: MY83-11501-AB is installed, and the date of manufacture is on or after 09/08/21 a new Engine Start/Stop Switch is not necessary.
  - If part number: MY83-11501-AB is installed, and the date of manufacture is on or before 08/08/21 a new Engine Start/Stop Switch must be installed.
  - If part number: MY83-11501-AA is installed, a new Engine Start/Stop Switch must be installed.
3. Install the Engine Start/Stop Switch (refer to Workshop Manual Procedure 64.01.EE).

### Warranty Data

#### Procedure and Labour Time

Description	Labour Time	ROT Code
Install Engine Start/Stop Switch	0.5	64.01.EE

#### Part Data

**Note: Dealers with 5 or more vehicles on the affected VIN list will be automatically supplied with an initial stock of Engine Start/Stop Switches. Please refer to Table 1 to see the initial supply volume for your dealership. It is not necessary for you to order these initial quantities.**

Description	Part Number	Quantity
Engine Start/Stop Switch	MY83-11501-AB	1

**Note: When you have completed this Service Action, make sure that you make an entry in Section A of the Vehicle Owner's Guide to show that the procedure is completed.**

Table 1

Dealer Name	DBX Vehicles Sold	Initial Supply of Engine Start/Stop Switches
ASTON MARTIN BOSTON	42	21
AM OF WASHINGTON DC LLC	27	14
AMLNA PRESS & MARKETING	27	14
ASTON MARTIN ATLANTA	17	9
ASTON MARTIN AUSTIN	29	15
ASTON MARTIN BEVERLY HILLS	73	37
ASTON MARTIN CALGARY	8	2
ASTON MARTIN CLEVELAND	14	7
ASTON MARTIN DALLAS	37	19
ASTON MARTIN DENVER	23	12
ASTON MARTIN DETROIT	14	7
ASTON MARTIN FORT LAUDERDALE	37	19
ASTON MARTIN GLENVIEW	21	11
ASTON MARTIN LAS VEGAS	12	6
ASTON MARTIN LIMA	4	0
ASTON MARTIN LOS GATOS	27	14
ASTON MARTIN MEXICO CITY	12	6
ASTON MARTIN MINNEAPOLIS	9	2
ASTON MARTIN NAPLES	34	17
ASTON MARTIN NASHVILLE	17	9
ASTON MARTIN NEWPORT BEACH	85	43
ASTON MARTIN OF CHARLOTTE	35	18
ASTON MARTIN OF LONG ISLAND	35	18
ASTON MARTIN OF SCOTTSDALE	12	6
ASTON MARTIN ONTARIO	23	12
ASTON MARTIN ORLANDO	17	9
ASTON MARTIN PALM BEACH	45	23
ASTON MARTIN RANCHO MIRAGE	31	16
ASTON MARTIN SAN DIEGO	26	13
ASTON MARTIN SANTIAGO	6	2
ASTON MARTIN SAO PAULO	2	0
ASTON MARTIN ST. LOUIS	18	9
ASTON MARTIN SUMMIT	21	11
ASTON MARTIN TAMPA BAY	31	16
ASTON MARTIN TORONTO	31	16
ASTON MARTIN VANCOUVER	14	7
ASTON MARTIN WALNUT CREEK	16	8
DECARIE MOTORS	24	12
F.C. KERBECK ASTON MARTIN	23	12
GALPIN ASTON MARTIN	38	19
MILLER MOTORCARS	53	27
NAPLETON'S ASTON MARTIN OF CHICAGO	32	16
PARK PLACE ASTON MARTIN	18	9
STAR MOTOR CARS	40	20
THE COLLECTION	74	37

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager. The English version of this document is written in Simplified Technical English to ASD-STE100™.