



## STAR ONLINE PUBLICATION



**Case Number:** S2108000108 REV. B

**Release Date:** March 2022

**Symptom/Vehicle Issue:** Interior Lamps Have A Momentary Delay After Opening A Door

**Customer Complaint/Technician Observation:** Owner complains the interior lamps have a delay to illuminate when the door is opened. Technician observed the delay to illuminate and a BCM setting DTC B1751-11 - COURTESY LAMP CONTROL-CIRCUIT SHORT TO GROUND.

**Discussion:** Vehicles equipped with sales code LCD incandescent interior lamp illumination may have a delayed interior lamp illumination response. The interior lighting will not fully illuminate when opening the door, the involved vehicles will have a few second delay. Vehicles equipped with the above condition should not have any repairs attempted, a software update is being validated and tentatively scheduled for release in the mid 2<sup>nd</sup> quarter 2022.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**