



NUMBER: 08-045-22

GROUP: 08 - Electrical

DATE: March 3, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-035, date of issue March 03, 2022. All applicable Sold and Un-Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

SUBJECT:

License Plate Lamp Harness Water Intrusion

OVERVIEW:

This bulletin involves replacing the rear bumper wiring harness.

MODELS:

2022 (DT) RAM 1500 Pickup

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

NOTE: This bulletin applies to vehicles built on or after November 04, 2021 (MDH 1104XX) and on or before November 05, 2021 (MDH 1105XX).

SYMPTOM/CONDITION:

The customer may experience the following:

• There is a potential for water intrusion which over time could lead to an inoperable license plate lamp.

NOTE:

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This only applies to vehicles on the RSU VIN list.**

PARTS REQUIRED:

Qty.	Part No.	Description
1	68488372AB	Bumper, Rear Wiring Harness

08-045-22 -2-

REPAIR PROCEDURE:

1. Remove the bumper. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info>13 - Frame and Bumpers / Bumper / Bumper, Rear / Removal.

NOTE: The new harness will come with new retainers (Fir Tree clips).

2. Replace the wiring harness with the new wiring harness (Fig. 1).




Fig. 1 Wiring Harness

3. Install the bumper. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info>13 - Frame and Bumpers / Bumper / Bumper, Rear / Installation .

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-90-21-92	Wire Harness, Rear Fascia/Bumper - Replace (2 - Skilled)	6 - Electrical and Body Systems	0.9 Hrs.

FAILURE CODE:

ZZ Service Action	
-------------------	--