

# Technical Journal

TITLE:

**PAS and/or CTA beeping/tone continuously on, ICUP system**

<b>REF NO:</b> TJ 36151.3.0	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2022-03-31	<b>STATUS DATE:</b> 2022-04-05
<b>FUNC GROUP:</b> 3900	<b>FUNC DESC:</b> Media, navigation and communication	Page 1 of 2	

“Right first time in Time”

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## Attachment

File Name	File Size
<a href="#">TJ_36151_2.mp4</a>	3.6202 MB

## DESCRIPTION:

\* Revised repair information under Service

\* Model type 539 added

If PAS and or CTA sound stays on continuously after a parking maneuver in narrow areas for example carwash or parking lots with obstacles along several sides of vehicle, please follow advice under “SERVICE”.

See attached video file for reference.

PAS = Park Assist Sensor

CTA = Cross-Traffic Alert

OTA = Over-The-Air software update

IHU = Infotainment Head Unit

# Technical Journal 36151.3.0

## CSC Customer Symptom Codes

Code	Description
KS	Front/rear park assist/Does not work
8Y	Audio other/Volume changes unexpectedly
FC	Audio other/Other audio problems
39	Sounds and speakers/Warning and notification sounds not audible

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
235							2022-9999		0175000-0999999	202122-999952
236							2022-9999		0144000-0999999	202122-999952
238							2022-9999		0245000-0999999	202122-999952
246							2022-9999		0899000-0999999	202122-999952
536	ED	E400V6					2021-9999		0000001-0999999	202037-999952
536	EF	E400V2					2022-9999		0640047-9999999	202146-999952
539							2022-9999		0000001-9999999	202139-999952

### SERVICE:

\*Improved IHU software released 3/28/22 in VIDA will prevent this symptom. It can be installed by downloading a Total Upgrade according to TJ 31543.

The same software will be released via OTA update during 22w14.

### Warranty claim info:

*To get warranty claim accepted for a job described in this TJ, please use warranty claim data as mentioned in TJ 31543.*

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3900.

**This TJ has one video file.**