

**SIB 33 01 20**

2022-04-20

**REAR AXLE SHUDDER AT SLOW SPEEDS**

This Service Information Bulletin (Revision 1) replaces SI B33 01 20 **dated January 2020**.

**What's New** (Specific text highlighted):

- New Software will be available in June 2022. Do not replace any parts

**MODEL**

G14 (8 Series Convertible)	G15 (8 Series Coupe)	G16 (8 Series Gran Coupe)
Vehicles with S-02T4 M Sport differential (rear axle differential with lock)		

**SITUATION**

**There is a shudder or jerking feeling coming from the rear of the vehicle at low speeds and low engine loads while turning**

**CAUSE**

Incorrect actuating pressure in the M-differential clutch plates.

**CORRECTION**

New software calibration.

**PROCEDURE**

**New software will be available in June 2022 to correct this issue.**

**An update to the SIB will be available when the software is released.**

**Note: A parts replacement will not remedy the situation and is therefore not advised.**

**QUESTIONS REGARDING THIS BULLETIN**

Technical inquires	Submit feedback at the top of this bulletin
Warranty inquires	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department