

CAMPAIGN LAUNCH STATUS

N681 UPDATE PRIOR TO SALE– FRONT LAMP UNIT SOFTWARE



UPDATE PRIOR TO SALE N681 FRONT HEADLAMP MODULE SOFTWARE UPDATE	
AFFECTED MODELS	2020-2023MY Defender
VOLUME AFFECTED	USA 151 CAN 34
REPAIR	Affected vehicles require a software update to the headlamp control system to ensure the vehicle is in line with the latest specification.
REPAIR TIME	0.2 hrs
CAMPAIGN LAUNCH	May 11 th , 2022
Notes	Affected vehicles must have this repair performed before retailer and customer delivery. At launch BBSS shows 53 affected units in retailer inventory.

