


TECHNICAL TOPICS

BODY/CHASSIS



Powered Loadspace Cover Does Not Open Correctly	22 – 23MY New Range Rover (L460)
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">– A customer may report that the powered loadspace cover does not open properly when actuated. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">– The loadspace cover may not initiate the fold properly due to incorrect hinge break point angle. <p><u>Status:</u></p> <ul style="list-style-type: none">– Engineering is currently investigating this concern.– SSM 75746 has been published to provide an interim solution to the concern.	 A technical cutaway diagram of the loadspace cover mechanism. It shows the cover in a partially open position, with various hinges, actuators, and structural components labeled with different colors (blue, green, yellow, red) to indicate specific parts of the assembly.

