


# TECHNICAL TOPICS

## BODY/CHASSIS



Approach Unlocking, Keyless Entry & Unlocking Inoperative	22MY New Range Rover (L460)
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- A customer may report that the Approach Unlocking or Keyless Entry and unlocking is inoperative with the smart key.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- The Remote Function Actuator (RFA) may not recognize the smart key properly. The vehicle can be unlocked using the emergency key blade and the engine can be started using the Immobilizer Antenna (IAU) by proper placement of the smart key.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- Engineering is currently investigating this concern.</li><li>- SSM 75742 has been published to provide a process to restore RFA operation.</li></ul>	 <p>The diagram illustrates the correct orientation of the smart key for the Remote Function Actuator (RFA). It consists of four numbered steps: 1. The key is held horizontally. 2. The key is tilted upwards. 3. The key is tilted downwards. 4. The key is tilted downwards, with a black arrow pointing to the bottom edge of the key, indicating the correct orientation for the RFA to recognize the key.</p>

