

<b>Reference</b>	SSM75713
<b>Models</b>	Discovery Sport / L550 New Range Rover Evoque / L551
<b>Title</b>	Noise from front brakes with 18-inch diameter brake system. 21 model years onwards.
<b>Category</b>	Chassis
<b>Last modified</b>	24-May-2022 00:00:00
<b>Symptom</b>	301000 Service Brake System
<b>Attachments</b>	1Brake noise.MOV (1Brake noise.MOV)

**Content**Issue:

Customers experience a 'graunch' noise when coming to a stop (dynamic to static) or a noise when releasing the brakes (static to dynamic). Please see attachment Video.

Cause:

Brake pad material properties.

Action:

Replace brake pads with high performance variant.

Land Rover Part Number: LR140729.

Thank you in advance for your assistance with this matter.

anBhdHRicnM7MjAyMj0wNS0yNF0xMT00Nj0zMS40NDFaOzEzN4yMjYyNTIuOTU7