

Subject: Gen 5 DD15 Proactive Exhaust Rocker Arm Replacement

Make: Freightliner

Model: New Cascadia

Model Year Affected: 2022

Build Date Range: Specific New Cascadia Vehicles Equipped with Gen 5 DD15 Engines

Our records indicate that you are the owner of certain vehicles, and DTNA has decided to share the following documentation with you.

Please see the attached communication in this email. We hope you find this information helpful.

Subject: Gen 5 DD115 Proactive Exhaust Rocker Arm Replacement

Make: Freightliner

Model: New Cascadia

Model Year Affected: 2022

Build Date Range: Specific New Cascadia Models Equipped with Gen 5 DD15 Engines

Exhaust Rocker Arm Replacement

Parts

Required Parts			
Part Description	Part Number	Quantity	Notes
Rocker Arm Service Kit	Provided by Detroit	6	Replace
Spacer Sleeve - Narrow	DDE A4720550451	6	As required
Spacer Sleeve - Wide	DDE A4720550351	6	As required

Work Instructions

1. Remove the exhaust rocker shaft assembly.
Refer to **Section 8.18.6 Removal of the Exhaust Rocker Shaft Assembly** in the **Gen 5 DD15 Platform Workshop Manual (DDC-SVC-MAN-0215)**.
2. Install a new exhaust rocker arm.
Refer to **Section 8.18.10 Replacement of the Exhaust or Engine Brake Rocker Arms** in the **Gen 5 DD15 Platform Workshop Manual (DDC-SVC-MAN-0215)**.
3. Install the exhaust rocker shaft assembly.
Refer to **Section 8.18.8 Installation of the Exhaust Rocker Shaft Assembly** in the **Gen 5 DD15 Platform Workshop Manual (DDC-SVC-MAN-0215)**.
4. Please return all removed exhaust rockers to the following address:
Detroit Diesel Corporation
12200 Telegraph Road
Redford, Michigan 48239
Attn: Return Material Room, Mark Aren